

July, 2022 - AHERA 3-Year Re-Inspection Report

Lower Nazareth Elementary School

4422 Newburg Road Nazareth, PA 18064

Prepared for:

Nazareth Area School District

One Education Plaza Nazareth, PA 18064

Prepared by:

Spotts, Stevens and McCoy

1047 North Park Road Reading, PA 19610 SSM Project 104016.0020

Inspected by:

William M. Katinowsky

PA Licensed Management Planner (#033689)

NAZARETH AREA SCHOOL DISTRICT LOWER NAZARETH ELEMENTARY SCHOOL AHERA 3-YEAR RE- INSPECTION REPORT JULY 2019

EXECUTIVE SUMMARY

The AHERA 3-Year Re-Inspection of the Lower Nazareth Elementary School was conducted by Mr. William M. Katinowsky on July 7, 2022. Mr. Katinowsky is an EPA AHERA accredited Building Inspector (BI), who is also licensed in the same capacity by the Pennsylvania Department of Labor and Industry (PaDLI). The inspection was performed in accordance with EPA 40 CFR, Part 763, which is commonly referred to as AHERA.

During the re- inspection, Mr. Kuchinski identified and assessed the condition of all known ACM, as noted in the previous inspections and re-inspections. There were no damaged materials found during this inspection. In areas where SSM could not identify ACM, as noted in the previous inspections and re-inspections, a note was added in the "comments" section of the room-by-room computer inventory.

BULK SAMPLING

There were no bulk samples collected during this inspection.

RESPONSE ACTIONS

Action 1: Approximately 500 square feet of asbestos-containing floor tile and associated mastic were removed from the Corridor near the Cafeteria bathrooms. Safeway Environmental was the abatement contractor. The abatement took place on June 13, 2022. Air Sampling was performed by SSM, 1047 North Park Road, Wyomissing PA, 19610. Reference report 104016.0020, dated June 17, 2022.

The Following was Highlighted in the February, 2022 6-Month Surveillance Report:

Removal of asbestos containing floor tile, mastic and blackboard/tack board mastic. Contractor, Prism Response, LLC, 70 Hillside Drive, Suite 200, Drums PA, 18222 Landfill, Amelia Landfill, 20221 Maplewood Road, Jetersville VA, 23083 Transport, N.E.T.S., 326 South Church St., Hazleton PA, 18201

Air monitoring was performed Spots, Stevens and McCoy, INC., 1047 North Park Road, Wyomissing PA, 19610, Reference report 104016.0017, dated August 23, 2021.

CONCLUSION

There were no other changes in condition and/or quantity of ACM discovered during this re-inspection. Continue to handle existing ACM in accordance with your current Operations and Maintenance (O&M) Plan. We also remind you to continue to provide maintenance and custodial staff with annual asbestos awareness training, continue to provide annual notification to building staff, parents and guardians, and to assure that copies of all inspection reports and AHERA documentation are maintained in your central AHERA files and at each individual school (Main Office in a location that is easily accessible by office staff).

Lower Nazareth Elementary School: Julyy 2022 3-Year Re-inspection Room-by-Room Inventory of Asbestos-containing Materials

									1	-71
F Comments	0 2525 SF abated June, 2021	1 Suggest sampling prior to renovations	1 Formerly Room 226	1 Formerly Room 227	0 500 S.F. abated June 2022	0 2525 SF abated June, 2021	0 635 SF abated June, 2021	0 500 SF abated June, 2021	0 900 SF abafed June 2021	1 Suggest sampling prior to renovations
ū	0	7	2	2	0	0	0	0	0	~
KF P	0	0	0	0	0	9	0	0	0	0
LT /	0	0	2	2	0	0	0	0	0	7
E	0	0	0	0	0	0	0	0	0	
Э(0	0	_	_	0	0	6	0	0	
S	202	SO	S	బ	S	S	S	20	SS	S
Quantity LS DC E AT AF PD F	0	Unknown	200	200	0	0	0	0	0	Unknown
Description	1' x 1' Tan & Brown Floor Tile and Mastic	Blackboard/Tack Board Mastic	1'x 1' Tan & Brown Floor Tile and Mastic	1'x 1' Tan & Brown Floor Tile and Mastic	Hallway by Flectric Room 1 x 1 Tan & Brown Floor Tile and Mastic	Hallway Front Bover 1' v 1' Tan & Brown Floor Tile and Mastic	11 x 11 Tan & Brown Floor Tile and Mastic	Black Mastic under Blue 1'x1' Floor Tile	Black Mastic Under Carpet or New Tile	П
Room	Cafeteria	Thronghont	Electric Room	School Store	Hallway by Flectric Room	Halkeav Front Tover	Health Boom	Main Office	Room 204	Throughout
Floor					, ,	4 4	-		-	-

Section 6-1: Recommended Minimum Response Actions for the Lower Nazareth Elementary School

Material & Location	Quantity	Response Action
Throughout Building 1'x1' Floor Tile and Mastic	400 S.F.	Handle Under O&M Program
Throughout Building Black Mastic under Carpet & New Tile*	Unknown	Handle Under O&M Program

S.F.= Square feet

^{*}Sample before disturbance

SECTION 6-2

NAZARETH AREA SCHOOL DISTRICT LOWER NAZARETH ELEMENTARY SCHOOL

RESPONSE ACTIONS TAKEN SINCE THE PREVIOUS RE-INSPECTION

The following response actions were taken in the Lower Nazareth Elementary School since the previous AHERA 3-year re-inspection:

Removal of:

 Approximately 4,050 square feet of asbestos-containing floor tile and associated mastic, approximately 2085 square feet of asbestos-containing mastic located beneath carpet or floor tile and approximately 200 square feet of asbestos-containing blackboard mastic.

Dates of Work

April 15, 2021 through June 27, 2021

Abatement Contractor

Prism Response 70 Hillside Drive Drums, PA

Landfill Information

Amelia Landfill

20221 Maplewood Rd.

Jetersville, VA

Transporter

N.E.T.S., Inc.

326 S. Church Street

Hazleton, PA

Air Monitoring

Air monitoring was performed SSM. Reference All reports for SSM Project Number 104016.0017.

 Approximately 4,050 square feet of asbestos-containing floor tile and associated mastic, approximately 2085 square feet of asbestos-containing mastic located beneath carpet or floor tile and approximately 200 square feet of asbestos-containing blackboard mastic.

Dates of Work

June 13, 2022

Abatement Contractor

Safeway Environmental 1255 Cedar Crest Blvd

Allentown, PA

Landfill Information

Amelia Landfill

20221 Maplewood Rd.

Jetersville, VA

Transporter

N.E.S.T., Inc

326 S. Church Street

Hazleton, PA

Air Monitoring

Air monitoring was performed SSM. Reference All reports for SSM Project Number 104016.0021.

TABLE 7-1

NAZARETH AREA SCHOOL DISTRICT LOWER NAZARETH ELEMENTARY SCHOOL ESTIMATED BUDGETARY COSTS FOR REMOVAL

Material	Quantity	Remove
1'x1' Floor Tile and Mastic	400 S.F.	\$4,000
Black Mastic under New Carpet or Tile	Unknown	Estimated S6/SF
		A + 000
	Total	\$4,000

Accreditations

Appendix A Annual Notifications



SPOTTS | STEVENS | MCCOY

ssmgroup.com

READING

1047 North Park Road; PO Box 6307 Reading PA 19610-0307 P. 610.621.2000 | F. 610.621.2001

LEHIGH VALLEY

Roma Corporate Center 1605 North Cedar Crest Boulevard; Suite 106 Allentown PA 18104 P. 610.849.9700 | F. 610.621.2001

LANCASTER

701 Creekside Lane Lititz PA 17543 P. 717.568.2678 | F. 610.621.2001