JM I Environmental Corp Swoyersville, PA (800) 828-1482 www.JMSIenviro.com

AHERA 6 Month Periodic Surveillance Inspection

Nazareth Area SD

January 2015

Lower Nazareth Elementary

Inspector: Dave J. Roberts 033732
Management Planner: Jeff J. Miller 025887

Functional Space	Material	Quantity	Current Condition	Previous Condition	Friable	Potential for Damage	Response Action
Cafeteria	12X12 VAT/Mastic (Tan & Brn)	2525 SF	Good	Good	No	Low	Maintain in Place
Room 226	12X12 VAT/Mastic (Tan)	200 SF	Removed by School				
Room 227	12X12 VAT/Mastic (Tan)	200 SF	Removed by School				
Old Section Hallway and Front Foyer	12X12 VAT/Mastic (Tan)	2555 SF	Good	Good	No	Low	Maintain in Place
Heath Room	12X12 VAT/Mastic (Tan)	635 SF	Good	Good	No	Low	Maintain in Place